



CAUTION
REPAIRS TO THIS
EQUIPMENT
MAY BE DANGEROUS

1113
ELECTRICAL
SPECIFICATIONS
DATE: 11/11/11
BY: [illegible]

NON
PCB

IN
LEVEL

1-1-1

7-2

1113

1113

1113

25
7.2X14.4
240/120

FILLED WITH OIL THAT
CONTAINED LESS THAN
1PPM PCBs AT TIME OF
MANUFACTURE.

WARNING

Hazardous voltage inside.

KEEP OUT!

Caution: Both environmentalists and
equipment operators must
handle this equipment with care.



WARNING

Underground power cables
are located in this area.

Before digging call 811.

Can shock, burn or cause death.



NOTICE



All users should read and follow the
operator's manual for this equipment.
This manual is located inside the
equipment. It is important to read the
manual before using the equipment.
If you have any questions, please
contact the manufacturer.

1
1
6
5
1
8



113

X1

E FORMCO
6847
V. 20 221 442 07251 20 501
1 21000112 1 214001114
478120 4136

OIL
LEVEL

**NON
PCB**

Barcode labels with alphanumeric codes and dates.


WARNING
PRECAUTION
INSTRUCTIONS













This page is intentionally left blank.



This page is intentionally left blank.



Step 1.

- Measure down from top of the cable a minimum of 11 1/2" (292 mm).
- Remove cable jacket (if jacketed cable is used) to expose neutral wires.
- Unwind neutral wires.
- Measure up 8" to 8 1/2" (203 to 216 mm) and make a square cut to remove excess cable.

Step 2.

- Measure down from the top of the cable 2 1/8" (54 mm).
- Remove the insulation and conductor shield to expose the bare conductor. Take care not to nick the conductor.

Step 3.

- Clean the exposed conductor using a wire brush.

Note: The probe (male contact) should be preassembled into the threads of the compression connector prior to crimping to ensure proper thread engagement.

- Place the coppertop (bimetal) connector on the conductor. Make sure the threaded hole in connector faces the apparatus bushing.

- Crimp the connector in place using a tool and die combination and minimum suggested number of crimps () as shown in **Table 1 on page 7**. Start crimping just below the knurled line and rotate each successive crimp to prevent bowing. Do not overlap crimps.
- Clean excess inhibitor grease from coppertop connector by wiping toward threaded eye.
- Smooth any sharp edges on the crimp connector surface.

Step 4.

- Measure down from the top of the connector 6 7/8" (175 mm).
- Remove the insulation shield. Take care not to nick or gouge the insulation.
- Place a 1/8" (3 mm) bevel on the insulation to ease elbow installation.

Note: If an Eaton's Cooper Power series standard elbow is used, proceed to Step 9. If Eaton's Cooper Power series integral jacket seal elbow is used, proceed to Step 5.